

General Environmental Incident Summary

Incident: 203 **Date/Time Notice:** 3/10/1994 1130 **DEM Incident No:**

Responsible Party: Lewis and Clark Reserve Center

Date Incident: 3/10/1994 **Time Incident:** **Duration:**

County: Burleigh **Twp:** 138 **Rng:** 80 **Sec:** 15 **Qtr:** SE

Lat: 46.77291 **Long:** -100.76300 **Method:** Derived from TRS

Location Description: NEXT TO UNITED TRIBES

Submitted By:

Affiliation:

Address:

City:

State:

Zip:

Received By:

Contact Person: Dale Rummel
3319 University Drive

Distance Nearest Occupied Building:

Type of Incident: HYDROCARBON

Description of Released Contaminant: Diesel fuel

Volume Spilled: 30.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance:

Reported to NRC: No

Cause of Incident:

TRUCK HAD A LEAK OVER WINTER. WILL USE ABSORBENT ON SATURATED ASPHALT.

Risk Evaluation:

of Fatalities:

of Injuries:

Affected Medium:

Potential Environmental Impacts:

Action Taken or Planned:

Wastes Disposal Location:

Agencies Involved:

