

General Environmental Incident Summary

Incident: 2112 **Date/Time Notice:** 11/15/2013 0840 **DEM Incident No:**

Responsible Party: Moe Oil

Date Incident: 11/14/2013 **Time Incident:** 1400 **Duration:**

County: Cass **Twp:** 138 **Rng:** 50 **Sec:** 1 **Qtr:**

Lat: 46.48519 **Long:** -96.96835 **Method:** Address matching

Location Description: Intersection of 64th Avenue South and 165th Aven SE, Horace, ND

Submitted By: Doug Murphy

Affiliation: Fargo Cass Public Health

Address: 401 3RD AVENUE NORTH

City: FARGO

State: ND

Zip: 58102

Received By:

Contact Person: Steve Stone
PO Box 181
Watertown, SD 57201

Distance Nearest Occupied Building:

Type of Incident: Tank Leak

Description of Released Contaminant: 50-100 gallons of diesel fuel.

Volume Spilled:

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Truck driver turned corner and rolled the loaded tanker truck into ditch.

Risk Evaluation:

N/A

of Fatalities: 0

of Injuries: 0

Affected Medium: 03 - soil

Potential Environmental Impacts:

Action Taken or Planned:

Wastes Disposal Location: Fargo Land Fill

Agencies Involved: State Highway Patrol, Local Fire Department, Local Emergency Manager

Updates

Date: 11/15/2013 **Status:** Reviewed - Assigned to NDDoH Division

Author: Roberts, Kris

Updated Volume:

Notes:

Release into road ditch near Horace. Followup is necessary. Referring to Fargo field office, initially to Christine Roob. The accident actually occurred at 168th Ave S and 43rd S (64th Ave S). According to Doug Murphy, the tanker on the truck never failed. LePier Oil Company of Foston, Minnesota came and pumped out the tanker. There was some antifreeze that leaked out on the gravel road, and Floor Dry was applied. There was a small leak in the saddle tank; a bucket was put under the leak and Floor Dry was used to capture the diesel that leaked on the ground. As a precaution, booms and pads were placed in the ditches on both sides of the road. Mike Hargiss and Christine Roob visited the site on November 15, 2013. The Floor Dry, pads and booms were cleaned up. There was a small amount of material soaked into the road bed and a very small area of hydrocarbon-stained grass and soil in the ditch. No further action is required.

Date: 12/18/2014 **Status:** Reviewed - No Action Required

Author: Tintes Schiwal, Emily

Updated Volume:

Notes:

NDDoH Fargo staff confirmed that this site was completely cleaned up the day of the incident and that no contamination issues remain. No further action is required.