

General Environmental Incident Summary

Incident 2133 **Date / Time of Notice** 12/4/2013 **DEM Incident Number:**
Responsible Party: Halliburton
Date Incident: 12/1/2013 **Time Incident:** 1225 **Duration:**
County: Stark **Twp:** 139 **Rng:** 99 **Sec:** 16 **Qtr:**
Lat: 46.85544 **Long:** -103.18930 **Method:** Interpolation from map
Location Description: US-85, approximately 12 miles south of Bellfield, ND
Submitted By: Ryan Campbell **Affiliation:** ERTS
Address 6001 Cochran Rd Suite 30 **City:** Solon
State: OH **Zip:** 44139

Received By:

Contact Person: Ryan Campbell
270 34th St. West
Dickinson, ND 58601

Distance Nearest Occupied Building:

Type of Incident Vehicle Accident

Description of Released Contaminant: UN1993 OilPerm FMM-1 Surfactant

Volume Spilled: **EPA Extremely Hazardous Substance:** No

Cause of Incident:

Tractor trailer hauling material was involved in a rollover accident. Product released from totes.

Risk Evaluation:

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Released material impacted the soil adjacent to the roadway.

Action Taken or Planned:

Environmental contractor dispatched to the site for initial response. The contaminated soils were secured for a pending excavation.

Wastes Disposal Location:

Updates

Date: 12/4/2013 Status: Reviewed; Followup Required Staff: Stockdill, Scott

Updated Volume: cubic yards

Truck rollover impacted areas off of road. Follow up necessary.