

General Environmental Incident Summary

Incident: 3293 **Date/Time Notice:** 4/18/2014 1322 **DEM Incident No:**
Responsible Party: All In Trucking
Date Incident: 4/17/2014 **Time Incident:** 1600 **Duration:** 5 minutes
County: McKenzie **Twp:** 150 **Rng:** 99 **Sec:** 24 **Qtr:** NE
Lat: 47.79793 **Long:** -103.28570 **Method:** Interpolation from map
Location Description: 202 3rd Ave. SW, Watford City, ND 58854 (West Lot)

Submitted By: Leigh Jennings **Affiliation:** Rolfson Oil, LLC, Corporate Couns
Address: 124 E. Fulton St.
Suite 404
City: Grand Rapids **State:** MI **Zip:** 49503

Received By:

Contact Person: Kristian Johnson
1106 18th St.
Williston, ND 58801

Distance Nearest Occupied Building: 100 Feet **Release Contained:** Yes
Type of Incident: Tank Overflow
Description of Released Contaminant: diesel fuel
Volume Spilled: 55.00 gallons **Ag Related:** No
EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

All In Trucking driver was unloading fuel to Rolfson tanks and overfilled tank on West lot. Driver shut pump off immediately.

Risk Evaluation:

No immediate health risks, potential fire hazard.

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Little to no likelihood of water impact as spill was in containment area and will be cleaned up shortly.

Action Taken or Planned:

Pump shut off. Fuel in containment area under tank. Pig blankets used to absorb fuel. Absorbent contacted and is giving quote to do the clean up work to remove contaminated soil inside the containment area.

Wastes Disposal Location: Absorbent to clean containment area and properly dispose of contaminants.

Agencies Involved:

Updates

Date: 4/18/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Volume:

Notes:

Release of diesel fuel from a tank overflow at the west Watford City Rolfson Oil depot. Followup is necessary.

Date: 4/23/2014 **Status:** Inspection

Author: Roberts, Kris

Updated Volume:

Notes:

4/23/14 - 09:30 on location. This and two other reported spills were inspected. This spill was in the west facility and was responded to using absorbents, pending further soil removal by contractor of the delivery jobber.

On-going issue with Rolfson Oil. This particular incident is only part. The incident, not the facility issue is closed.