

# General Environmental Incident Summary

**Incident:** 3381      **Date/Time Notice:** 7/12/2014      0930      **DEM Incident No:**  
**Responsible Party:** Deer Valley Trucking, Inc.  
**Date Incident:** 7/11/2014      **Time Incident:** 1345      **Duration:** 2 hours  
**County:** Williams      **Twp:** 156      **Rng:** 95      **Sec:** 18      **Qtr:**  
**Lat:** 48.34173      **Long:** -102.93690      **Method:** Interpolation from map  
**Location Description:** Hwy 2 Eastbound in turn lane to state hwy 40 northbound. Tioga

**Submitted By:** Rick Thompson      **Affiliation:** Compliance Director, Deer Valley T  
**Address:** 310 Airport Rd.  
Suite 700  
**City:** Williston      **State:** ND      **Zip:** 58801

## Received By:

**Contact Person:** Rick Thompson  
310 Airport Rd.  
Suite 700  
Williston, ND 58801

**Distance Nearest Occupied Building:**      **Release Contained:** Yes

**Type of Incident:** Tank Overflow

**Description of Released Contaminant:** EcoFlow NE

**Volume Spilled:** 4.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** Unknown

## Cause of Incident:

Slosh in tank caused some of the product to escape from a unsecured hatch lid on top of the tank. Of the 4 gallons spilled, 3 of the gallons were contained on the asphalt roadway. Approximately 1 gallon spilled off of the asphalt onto the dirt on the shoulder of the road where it was contained and cleaned up.

## Risk Evaluation:

EcoFlow NE is a combustable liquid. Because it was immediately contained, immediate risk was minimal.

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

## Potential Environmental Impacts:

No environmental impacts will occur.

## Action Taken or Planned:

The driver stopped the truck immediately, put down absorbent pads and absorbent "kitty litter". Driver then called 911 to report the spill and request local law enforcement for traffic control. Driver then called his employer, Deer Valley Trucking, Inc. to report the incident and request assistance in cleanup. Driver then called the company that owned the tank and product he was hauling, Independence Oilfield Chemicals, LLC., to report the incident and request assistance in cleanup.

Staff from both companies arrived and shoveled up the affected soil near the road, kitty litter, and absorbent rags and placed them in a yellow spill containment drum.

***Wastes Disposal Location:***

***Agencies Involved:*** State Highway Patrol, Local Fire Department

***Updates***

---

***Date:*** 7/12/2014    ***Status:*** Correspondence

***Author:*** Roberts, Kris

***Updated Volume:***

***Notes:***

7/12/14 - Spoke with driver after being called by EP&R. He explained incident and the response. Release was small, and response was quick and complete. No on-site inspection necessary.