

General Environmental Incident Summary

Incident: 3715 **Date/Time Notice:** 4/10/2015 1515 **DEM Incident No:**
Responsible Party: Dakota Prairie Refining, LLC

Date Incident: 4/10/2015 **Time Incident:** 1505 **Duration:** 1 minutes

County: Stark **Twp:** 139 **Rng:** 97 **Sec:** 15 **Qtr:**

Lat: 46.86023 **Long:** -102.89450 **Method:** Interpolation from map

Location Description: 3815 116th Ave SW
Dickinson, ND 58601

Submitted By: Jean Butterfield **Affiliation:**

Address: 3815 116th Ave SW

City: Dickinson **State:** ND **Zip:** 58601

Received By:

Contact Person: David Podratz
3815 116th Ave SW
Dickinson, ND 58601

Distance Nearest Occupied Building: 1 Miles **Release Contained:** Yes

Type of Incident: Pipeline Leak

Description of Released Contaminant: crude oil

Volume Spilled: 5.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

lose flange in pipe rack allowed small amount, <5 gallons, of crude to leak out

Risk Evaluation:

no immediate risk

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

no impact to environment, the small spill was immediately cleaned up

Action Taken or Planned:

flange was tightened to stop leak and contaminated soil was put into a drum for disposal

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 4/10/2015 **Status:** Reviewed - No Action Required

Author: Espe, Brady

Updated Volume:

Notes:

This spilled occurred on a facility that is engineered to handle spills.