

General Environmental Incident Summary

Incident: 3722 **Date/Time Notice:** 4/15/2015 0936 **DEM Incident No:**
Responsible Party: ONEOK Rockies Midstream
Date Incident: 4/10/2015 **Time Incident:** 0815 **Duration:** 30 minutes
County: McKenzie **Twp:** 154 **Rng:** 99 **Sec:** 7 **Qtr:**
Lat: 48.17640 **Long:** -103.47280 **Method:** Navigation quality GPS
Location Description: Epping

Submitted By: Merlyn Counsell **Affiliation:** BCES
Address: 5241 142nd Drive NW
City: Williston **State:** ND **Zip:** 58802

Received By:

Contact Person: Nadia Kyrlova
2700 Lincoln Ave SE
Sidney, MT 59270

Distance Nearest Occupied Building: 0.5 Miles **Release Contained:** Yes

Type of Incident: Normal hose wear

Description of Released Contaminant: Hydraulic oil

Volume Spilled: 0.13 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Normal wear on the Hydraulic hose on a loader unit.

Risk Evaluation:

None

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

None

Action Taken or Planned:

Soil was shoveled into sacks and transported to containment drum at BCES field lay down yard for disposal. Machine was wiped down and pads taken to containment drum also.

Wastes Disposal Location: IHD Environmental; Williston, North Dakota

Agencies Involved:

Updates

Date: 4/15/2015 **Status:** Reviewed - No Action Required

Author: Stockdill, Scott

Updated Volume:

Notes:

According to the report, normal wear on a hydraulic hose leaked 0.125 gallons of hydraulic oil on to the ground. Impacted soil was removed and placed in sacks for transport to collection drums for disposal at IHD. No on-site followup required at this time.