

General Environmental Incident Summary

Incident: 3811 **Date/Time Notice:** 7/7/2015 1430 **DEM Incident No:**
Responsible Party: QC ER Texas
Date Incident: 11/24/2014 **Time Incident:** 2300 **Duration:** 10 minutes
County: Dunn **Twp:** 145 **Rng:** 95 **Sec:** 10 **Qtr:**
Lat: 47.39362 **Long:** -102.76990 **Method:** Interpolation from map
Location Description: Trucking terminal facility

Submitted By: George Sabo **Affiliation:**
Address: 6001 Cochran
City: Solon **State:** OH **Zip:** 44139

Received By:

Contact Person: Jim Rakitsky
102 Pickering Way
Exton , PA 19341

Distance Nearest Occupied Building: **Release Contained:** Yes

Type of Incident: Tank Leak

Description of Released Contaminant: Brine water post injection

Volume Spilled: 420.00 gallons **Ag Related:** No

EPA Extremely Hazardous Substance: Unknown **Reported to NRC:** Unknown

Cause of Incident:

Due to pipeline failure salt water was released to the soil containment area,

Risk Evaluation:

no immediate risk to health

of Fatalities: **# of Injuries:** **Affected Medium:** 03 - soil

Potential Environmental Impacts:

Release was to containment so minimal potential impact to environmental

Action Taken or Planned:

Area was re mediated. Incident was reported to NDIC State Inspector Dan Wiggin 701-441-9010.

Wastes Disposal Location: The waste is currently staged at Clean Harbors pending NORM analyticals

Agencies Involved:

Updates

Date: 7/15/2015 **Status:** Reviewed - Follow-up Required

Author: Suess, Bill

Updated Volume:

Notes:

Release occurred on a non E& P facility and required follow-up.

Date: 7/20/2015 **Status:** Inspection

Author: Espe, Brady

Updated Volume:

Notes:

I talked to the manager of the facility. He indicated that the spill occurred on the Spletsoter 43-8 south of Plaza, ND. This spill was submitted as incident 20141124150007 o the NDIC. The spill stayed on the facilicy and is NDIC oversight. He also indicated that this report was submitted by a company service that the corporate office used and since then, they no longer use this service.