

General Environmental Incident Summary

Incident: 4090 **Date/Time Notice:** 5/7/2016 0714 **DEM Incident No:**
Responsible Party: Kinder/Morgan
Date Incident: 5/7/2016 **Time Incident:** 0716 **Duration:** 12 hours
County: Barnes **Twp:** 142 **Rng:** 60 **Sec:** 24 **Qtr:**
Lat: 47.10440 **Long:** -98.22279 **Method:** Interpolation from map
Location Description: 1.9 miles North of Rogers North Dakota traveling on ND Hwy 1, then 3.6 miles West on Hwy 9, pump station is on North Side of road.

Submitted By: Ann Osborne **Affiliation:**
Address: 2215 105th Ave SE
City: Rogers **State:** ND **Zip:** 58479

Received By:

Contact Person: Todd Nelson
750 S Elmhurst Rd
Elk Grove Village, IL 60007

Distance Nearest Occupied Building: 1.5 Miles **Release Contained:** Yes

Type of Incident: Tank Leak

Description of Released Contaminant: Condensate

Volume Spilled: **Ag Related:** No

EPA Extremely Hazardous Substance: No **Reported to NRC:** Unknown

Cause of Incident:

Valve was leaking at site, work crew had been out the evening before doing work on the area, valve had leaked throughout the night and into the next morning. A passerby had noticed a propane/natural gas smell and called their concerns in.

Risk Evaluation:

There were no immediate or long term health risks associated with this release

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

The release was contained completely on the facility soil. There were no impacts to ground or surface water

Action Taken or Planned:

The Dazey Fire Department was dispatched to the scene, and called for a shelter in place for neighboring farms. The Company was notified and replaced the malfunctioning valve, a clean up crew was dispatched along with a vacuum truck, a small dike was built to contain any chemical the crew is letting it wick out to holes and from the holes, they are then hydro-vacuuming it up. Crews also have tarps available and ready in case of rain they will be able to cover the exposed area.

Wastes Disposal Location: Waste will be removed to a certified disposal location.

Agencies Involved: NDDDES, Local Law Enforcement, Local Emergency Manager, Dazey Fire

Updates

Date: 5/7/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Volume:

Notes:

According to the report, natural gas condensate was released during a tank leak onto facility soil. More follow-up needed.

Date: 5/11/2016 **Status:** Correspondence

Author: O'Gorman, Brian

Updated Volume:

Notes:

Spoke with Kinder Morgan representative on site 5/10/16. This report (#4090) is a duplicate entry for #4088. They wanted to update the volume; however, no volume was added to this report. Please refer to incident #4088 for a complete overview of this reported incident.