

# General Environmental Incident Summary

**Incident:** 4163      **Date/Time Notice:** 7/12/2016      1200      **DEM Incident No:**

**Responsible Party:** Renaissance Transport Ltd

**Date Incident:** 7/11/2016      **Time Incident:** 1500      **Duration:**

**County:** Ward      **Twp:** 161      **Rng:** 88      **Sec:** 23      **Qtr:** NW NW

**Lat:** 48.76362      **Long:** -102.06450      **Method:** Interpolation from map

**Location Description:** From the east junction of 5 + 52, 1 mile east

**Submitted By:** Ernie Kotyluk

**Affiliation:**

**Address:** Box 46 site 145 rr 1

**City:** Brandon

**State:** MB

**Zip:** R7A5Y1

**Received By:**

**Contact Person:**

Box 46 site 145 rr 1

Brandon, MB

**Distance Nearest Occupied Building:** 1000 Feet

**Release Contained:** Yes

**Type of Incident:** Vehicle Accident

**Description of Released Contaminant:** PG-64-28 asphalt oil

**Volume Spilled:** 300.00 gallons

**Ag Related:** No

**EPA Extremely Hazardous Substance:** No

**Reported to NRC:** Unknown

**Cause of Incident:**

Driver swerved to avoid deer causing the pup to move off the pavement. Since there is no shoulder the pup trailer was pulled into the ditch and separated from the lead trailer. It came to rest with the lid pointing down and product slowly leaking out the relief valve.

**Risk Evaluation:**

zero risk of any kind

**# of Fatalities:** 0

**# of Injuries:** 0

**Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

100 percent of the spilled product is removed, zero chance of impact

**Action Taken or Planned:**

Farden Construction from Kenmare responded within an hour of the incident and promptly had the trailer back on its wheels and delivered it to the asphalt plant where it was originally destined. The next morning (July 12) they excavated the site, removing the hardened asphalt and graded the ditch appropriately when finished.

**Wastes Disposal Location:** The recovered dirt and asphalt will be recycled at the asphalt plant at Glenburn.

**Agencies Involved:** State Highway Patrol

## **Updates**

---

**Date:** 7/12/2016    **Status:** Reviewed - Follow-up Required

**Author:** Souder, Taylor

**Updated Volume:**

**Notes:**

Further follow-up needed.

---

**Date:** 7/20/2016    **Status:** Correspondence

**Author:** Kangas, Kathleen

**Updated Volume:**

**Notes:**

NOTE: Submitted location is incorrect. After consulting with the company rep, the correct location was finally determined. This site is in Ward County, not Bottineau. The township, range, and section are also incorrect. The correct location is approximately 1 mile east of the intersection of Hwy 5 and 52 near Kenmare, directly to the east of 492 St NW. The database and main record have been updated to reflect the correct location, which is given below.

S23, T161N, R88W  
Quarter: NW 1/4 of NW 1/4  
Ward County

Lat/Long: 48.763623, -102.064514

---

**Date:** 7/21/2016    **Status:** Inspection

**Author:** Kangas, Kathleen

**Updated Volume:**

**Notes:**

On site at 4:00 p.m. 86 degrees. Hot and humid. Partly cloudy, light wind. The spill is located on the south side of the road. Site appears remediated. No asphalt oil appeared to remain.