

# General Environmental Incident Summary

**Incident:** 711      **Date/Time Notice:** 7/22/2004      1509      **DEM Incident No:**  
**Responsible Party:** Ron Koester  
**Date Incident:** 7/20/2004      **Time Incident:** 1005      **Duration:** 20 minutes  
**County:** Pembina      **Twp:** 159      **Rng:** 51      **Sec:** 14      **Qtr:** NW SE SE  
**Lat:** 48.59303      **Long:** -97.17905      **Method:** Derived from TRS  
**Location Description:** 8152 County Highway 44 North, Drayton, ND  
between the pulp pellet storage bins and the "new" warehouse

**Submitted By:** Steve Lindquist      **Affiliation:**

**Address:**

**City:**      **State:**      **Zip:**

**Received By:**

**Contact Person:** Steve Lindquist  
American Crystal Sugar Company  
County Highway 44 North  
Drayton, ND 58225-0190

**Distance Nearest Occupied Building:** 100 Feet

**Type of Incident:** tank leak

**Description of Released Contaminant:** used lubrication oil (not automobile)

**Volume Spilled:** 100.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** No

**Cause of Incident:**

The used oil tank's nozzle was accidentally sheared off by a contractor.

**Risk Evaluation:**

none

**# of Fatalities:** 0      **# of Injuries:** 0      **Affected Medium:** 03 - soil

**Potential Environmental Impacts:**

The bulk was on concrete. Some went on grass and some into some stagnant standing water

**Action Taken or Planned:**

Corn-based absorbant took the oil off the concrete. The soil/grass was removed. The water was skimmed and wet-vacuumed. All of these were placed in 55 gallon drums.

**Wastes Disposal Location:** The soil and oil will be burned in ACSC's main boiler in September when it is started (we have a used oil burning permit)

**Agencies Involved:**

