

Oil Field Environmental Incident Summary

Incident: 20130111093531 **Date/Time of Notice:** 01/11/2013 09:07

Responsible Party: Atlas Oilfield Construction

Well Operator: BOREJAKS ENERGY SERVICES

Well Name: NYGAARD SWD 1

Field Name: RAWSON

Well File #: 90216

Date Incident: 11/7/2012 **Time Incident:** 0400

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 101

Sec: 14

Qtr: SW SE

Location Description:

Submitted By: Sean Mccabe

Received By:

Contact Person: Sean Mccabe
520 CENTRAL PARKWAY EAST
SUITE 107
PLANO, TX 75074

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Fire

Release Contained in Dike: Unknown

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units
Oil	0	barrels	0	barrels
Brine	0	barrels	0	barrels
Other	0	barrels	0	barrels

Followup **Units**

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

Action Taken or Planned:

Excess lime use was due to equipment not operating properly. Equipment has been repaired and lime is used less.

Wastes Disposal Location: Solid was transported to a landfill.

Agencies Involved: Local Fire Department

Updates

Date: 1/11/2013 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Fire reported. Apparently no fluids left location.