

Oil Field Environmental Incident Summary

Incident: 20130228160941 **Date/Time of Notice:** 02/28/2013 16:02
Responsible Party: Petro Harvester Operating Company, LLC
Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC
Well Name: EVENSON 1-R
Field Name: WAYNE **Well File #:** 0
Date Incident: 2/21/2013 **Time Incident:** 07:30 **Facility ID Number:** 209091-1
County: BOTTINEAU **Twp:** 162 **Rng:** 81 **Sec:** 31 **Qtr:** NE NW
Location Description: Mist on snow NW of treater

Submitted By: Ben Tohm **Received By:**

Contact Person: Ben Tohm
5160 TENNYSON PARKWAY
SUITE 3000 E
PLANO, TX 75024

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 2 Miles

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Unknown

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	5	gallons	5	gallons		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Areal Extent:

Approx 5 ft NW between tank dike and flare pit

Potential Environmental Impacts:

Action Taken or Planned:

Shut in and drained treater, replaced gasket.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 2/28/2013 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release is reported to have remained on location, between treater and flare.