

# Oil Field Environmental Incident Summary

**Incident:** 20130909132059      **Date/Time of Notice:** 09/09/2013 13:19

**Responsible Party:** Zenergy, Inc.

**Well Operator:** ZENERGY, INC

**Well Name:** FAIRVIEW OVERLOOK 34-33HTF

**Field Name:** HARDING

**Well File #:** 25465

**Date Incident:** 9/9/2013      **Time Incident:** 10:50

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 151      **Rng:** 104      **Sec:** 34      **Qtr:**

**Location Description:**

**Submitted By:** Chad Hillesland

**Received By:**

**Contact Person:** Chad Hillesland  
6100 S YALE AVE STE 1700  
TULSA, OK 74136

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Miles

**Distance Nearest Water Well:** 1 Miles

**Type of Incident:** Blowout

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2	barrels	0	barrels		
<b>Brine</b>	0	barrels	0	barrels		
<b>Other</b>	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None.

**Areal Extent:**

**Potential Environmental Impacts:**

None.

**Action Taken or Planned:**

Rams were manually closed immediately to stop the blowout. Vac truck was called to location to commence clean-up activities.

**Wastes Disposal Location:** Tervita

**Agencies Involved:**

**Updates**

---

**Date:** 9/9/2013    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Blowout release remained on location, within diking, according to the report. Will assume that is correct unless we hear differently from O&G inspection.