

# Oil Field Environmental Incident Summary

**Incident:** 20131120101559      **Date/Time of Notice:** 11/20/2013 09:15

**Responsible Party:** Helmerich & Payne

**Well Operator:** MARATHON OIL COMPANY

**Well Name:** SKOLD 34-35TFH

**Field Name:** REUNION BAY

**Well File #:** 26461

**Date Incident:** 11/13/2013      **Time Incident:** 09:15

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 150

**Rng:** 93

**Sec:** 2

**Qtr:** LO T3

**Location Description:**

**Submitted By:** Ashley Schaper

**Received By:**

**Contact Person:** Larry Price  
3172 HWY 22 N  
DICKINSON, ND 58601

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** Unknown

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0	barrels	0	barrels		
<b>Brine</b>	0	barrels	0	barrels		
<b>Other</b>	20	barrels	20	barrels		

**Description of Other Released Contaminant:**

Oil Based Mud

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

**Areal Extent:**

**Potential Environmental Impacts:**

No potential environmental impacts all of the material was contained on the rig matting nothing came in contact with unprotected soil.

**Action Taken or Planned:**

Clean up was immediate it was sucked up with Rig Vac no fluids went off of the rig matting or liner.

**Wastes Disposal Location:** The mud was recycled and put back into the mud system

**Agencies Involved:**

**Updates**

---

**Date:** 11/20/2013 **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release of drilling mud, during drilling activities, remained on location, according to the report.