

Oil Field Environmental Incident Summary

Incident: 20131202082445 **Date/Time of Notice:** 12/02/2013 08:19

Responsible Party: Zenergy, Inc.

Well Operator: ZENERGY, INC

Well Name: OMLID 18-19HTF

Field Name: ELIDAH

Well File #: 20761

Date Incident: 11/28/2013 **Time Incident:** 11:30

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 97

Sec: 18

Qtr: NE NW

Location Description:

Submitted By: Chad Hillesland

Received By:

Contact Person: Chad Hillesland
6100 S YALE AVE STE 1700
TULSA, OK 74136

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 0.5 Miles

Distance Nearest Water Well: 0.5 Miles

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	barrels	1	barrels	1	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 12/2/2013

Clean Up Concluded: 11/29/2013

Risk Evaluation:

None.

Areal Extent:

Potential Environmental Impacts:

None.

Action Taken or Planned:

Closed valve between FW lines and casing injection point at the wellhead, called vac truck to suck up fluid, repair connection and replace check valve.

Wastes Disposal Location: SW tank on location.

Agencies Involved:

Updates

Date: 12/2/2013 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release was contained on location, according to the report. NDIC retains oversight.