

Oil Field Environmental Incident Summary

Incident: 20131207093305 **Date/Time of Notice:** 12/07/2013 09:22

Responsible Party: XTO Energy

Well Operator: XTO ENERGY INC.

Well Name: CLYDE HAUGE 11X-13

Field Name: DOLLAR JOE

Well File #: 21495

Date Incident: 12/6/2013 **Time Incident:** 0832

Facility ID Number:

County: WILLIAMS

Twp: 155 **Rng:** 97 **Sec:** 13 **Qtr:**

Location Description:

Submitted By: Shawn Dahl

Received By:

Contact Person:

P.O Box 1589
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units
Oil	1	barrels	0	barrels
Brine	0	barrels	0	barrels
Other	0	barrels	0	barrels

Followup **Units**

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Spill was contained in the metal berm. Lease operator is going to produce into 2 tanks until the well settles down

Wastes Disposal Location: impacted soil will be taken to pdi

Agencies Involved:

Updates

Date: 12/9/2013 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, this incident remained within the dikes on location. NDIC retains oversight.