

# Oil Field Environmental Incident Summary

**Incident:** 20131209094943      **Date/Time of Notice:** 12/09/2013 09:37

**Responsible Party:** Power Fuels

**Well Operator:** OXY USA INC.

**Well Name:** STATE JAEGER B 7-27-34H-144-97

**Field Name:** CABERNET

**Well File #:** 26096

**Date Incident:** 12/9/2013      **Time Incident:** 230

**Facility ID Number:**

**County:** DUNN

**Twp:** 144      **Rng:** 97      **Sec:** 22      **Qtr:**

**Location Description:** Fresh water spill started on location, 2 bbls of water ran off location onto adjacent pasture land

**Submitted By:** Dustin Tescher

**Received By:**

**Contact Person:** Dustin Tescher  
5 GREENWAY PLAZA STE 110  
HOUSTON, TX 77046-0506

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0	barrels	0	barrels		
<b>Brine</b>	0	barrels	0	barrels		
<b>Other</b>	15	barrels	2	barrels		

**Description of Other Released Contaminant:**

Fresh water

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

No risk

**Areal Extent:**

20ftx10ft

**Potential Environmental Impacts:**

No impact, spill was fresh water

**Action Taken or Planned:**

Valves were shut to isolate and stop the release.

**Wastes Disposal Location:** NA

**Agencies Involved:**

**Updates**

---

**Date:** 12/9/2013    **Status:** Inspection

**Author:** Clary, Shane

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

After speaking with the company contact, it was confirmed that this was a fresh water spill. Power Fuels only carries fresh water for OXY USA INC. After inspecting the location, this does appear to only have been fresh water. A follow-up inspection in the spring will be conducted to verify.

---

**Date:** 12/12/2013    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Reported freshwater release ran off location into pasture. Followup is necessary to confirm freshwater quality.

---

**Date:** 10/12/2015 **Status:** Inspection

**Author:** Crowdus, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On location 10/12/2015, at 4:14 p.m. Walked the perimeter of pad. There does not appear to be any impact to vegetation at this time. No further follow-up required.