

Oil Field Environmental Incident Summary

Incident: 20131223084728 **Date/Time of Notice:** 12/23/2013 08:34

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: HAUSTVEIT 42X-10

Field Name: CAPA

Well File #: 19344

Date Incident: 12/22/2013 **Time Incident:** 1122

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 95

Sec: 10

Qtr:

Location Description:

Submitted By: Scot Richardson

Received By:

Contact Person: Scot Richardson
P.O Box 6506
Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2.5	barrels	2	barrels		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Spill was contained in unlined berm and well was shutin. Vaccum truck picked up free liquids and placed them back into production tank. Roustabout will clean up location and remove impacted soils.

Wastes Disposal Location: Indian Hills Disposal

Agencies Involved:

Updates

Date: 12/23/2013 **Status:** Reviewed - Assigned to Other Agency

Author: Miller, Adam

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spill, due to unspecified cause, remained on location, within berm. NDIC retains oversight.