

Oil Field Environmental Incident Summary

Incident: 20140106165455 **Date/Time of Notice:** 01/06/2014 16:47

Responsible Party: Chuck Cornelius

Well Operator: ENDURO OPERATING, LLC

Well Name: BURNING MINE BUTTE 9-21

Field Name: BURNING MINE

Well File #: 9362

Date Incident: 12/31/2013 **Time Incident:** 08.00

Facility ID Number:

County: MCKENZIE

Twp: 147

Rng: 102

Sec: 9

Qtr:

Location Description:

Submitted By: Chuck Cornelius

Received By:

Contact Person: Chuck Cornelius
777 MAIN STREET
SUITE 800
FORT WORTH, TX 76102

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Miles

Distance Nearest Water Well: 1 Miles

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: Unknown

| | Spilled | Units | Recovered | Units | Followup | Units |
|--------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| Oil | 5 | barrels | 5 | barrels | | |
| Brine | 0 | barrels | 0 | barrels | | |
| Other | 0 | barrels | 0 | barrels | | |

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

none

Action Taken or Planned:

Contained in dike. Used hot oiler to clean tank and ground. Repair treater. Oil to stiff to equalize to other tank used for over flow.

Wastes Disposal Location: Tervita Alexander ND

Agencies Involved: Forest Service

Updates

Date: 1/10/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from tank overflow remained on location, within the diking, according to the report. NDIC retains oversight.