

Oil Field Environmental Incident Summary

Incident: 20140117173412 **Date/Time of Notice:** 01/17/2014 05:15

Responsible Party: Great Western Resources, LC

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name:

Field Name:

Well File #: 0

Date Incident: 1/17/2014

Time Incident: 5:15a

Facility ID Number:

County: WILLIAMS

Twp: 156

Rng: 98

Sec: 34

Qtr:

Location Description: Two or so mile stretch of county road 119 th ave nw and county road 60 th st. NW, a small hose leak that dripped intermittently onto mid section of roadway.

Submitted By: Bill Howell

Received By:

Contact Person: Bill Howell

5401 Highway 8

Stanley, ND 58784

General Land Use: Other - Described Above

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Unknown

Reported to NRC: Unknown

| | Spilled | Units | Recovered | Units |
|--------------|----------------|--------------|------------------|--------------|
| Oil | 0 | barrels | 0 | barrels |
| Brine | 1 | barrels | 0 | barrels |
| Other | 0 | barrels | 0 | barrels |

Followup **Units**

Description of Other Released Contaminant:

n/a

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Potential Environmental Impacts:

The minor dripping onto roadway should present no impact to other areas.

Action Taken or Planned:

We are waiting to hear from the Williams County road officials as to what they may suggest or require as far as the removal of traces of spill are concerned.

Wastes Disposal Location: As directed by the county / state, if any.

Agencies Involved: Williams County

Updates

Date: 1/21/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

This release by truck on to private and public roads. This was reported initially by CRI to O&G Williston supervisor who contacted Roberts. Followup with O&G and CRI necessary for investigation.

Date: 1/24/2014 **Status:** Correspondence

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Phone contact with John Axtman of NDIC; they had inspected the report and had found the impacts to the roadway difficult to detect. Will call report contact next week to get update.

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Phone call with responsible party personnel. According to personnel, ultimate source of spill not determined. Company gathered two 32-gal trash cans of material scraped off the county road and combined this material at company's yard with impacted material from another spill cleaned up by JMAC. Total material sent for disposal to Indian Hills.