

Oil Field Environmental Incident Summary

Incident: 20140129151456 **Date/Time of Notice:** 01/29/2014 14:55
Responsible Party: PHLLC
Well Operator: PETRO-HUNT, L.L.C.
Well Name: WISNESS 152-96-28A-33-3H
Field Name: KEENE **Well File #:** 22440
Date Incident: 1/1/1900 **Time Incident:** 13:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 152 **Rng:** 96 **Sec:** 28 **Qtr:** NW NE

Location Description:

Submitted By: DOUG HANSON **Received By:**
Contact Person: DOUG HANSON
1500 13TH ST SW
KILLDEER, ND 58640

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building: 1.2 Miles
Distance Nearest Water Well: 1.2 Miles

Type of Incident Tank Overflow

Release Contained in Dike	No			Reported to NRC:	No	
	Spilled	Units	Recovered	Units	Followup	Units
Oil	15	barrels	15	barrels		
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:
NONE

Areal Extent:
A SMALL MIST OF OIL WENT OFF THE SITE ABOUT 100 FEET, ESTIMATED LESS THAN ONE BARREL.

Potential Environmental Impacts:

THE MAJORITY OF FLUID CAPTURED INSIDE THE LINED METAL DIKES WAS EASILY PICKED UP. THE LAND OWNER HAS ASKED US TO PICK UP SOME STAINED SNOW WHICH HAD A MIST OF OIL.

Action Taken or Planned:

THE WELL WAS SHUT IN AND FLOW CURTAILED. THE CLEAN UP BEGAN WITH VAC-TRUCKS PICKING UP FLUIDS, AND WASHING TANKS. SOME STAINED SNOW JUST OUTSIDE THE DIKES OFF LOCATION IS BEING PICKED UP.

Wastes Disposal Location: ALL FLUIDS INCLUDING SNOWS WILL BE RECYCLED, ON THE LOCATION.

Agencies Involved:

Updates

Date: 1/30/2014 **Status:** Reviewed; Followup Required **Staff:** Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from tank overflow sprayed off location, according to the report. Followup is necessary. Incident date incorrect. Please correct during inspection.