

Oil Field Environmental Incident Summary

Incident: 20140130111215 **Date/Time of Notice:** 01/30/2014 11:01

Responsible Party: EOG Resources, Inc.

Well Operator: EOG RESOURCES, INC.

Well Name: LUCILLE 22-06H

Field Name: PARSHALL

Well File #: 18171

Date Incident: 1/29/2014 **Time Incident:** 17:00

Facility ID Number:

County: MOUNTRAIL

Twp: 153

Rng: 90

Sec: 6

Qtr: SE SE

Location Description: Lite spray on farmed area to SE of flare pit

Submitted By: Luigi Heydt

Received By:

Contact Person: Luigi Heydt
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	barrels	0	barrels	0	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/5/2014

Clean Up Concluded: 1/30/2014

Risk Evaluation:

Areal Extent:

Potential Environmental Impacts:

Action Taken or Planned:

Rattigans were closed to stop flow. The area on the location and the farmed area the snow and affected soil were removed and hauled to disposal.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 1/30/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from apparent treater upset sprayed off location to the SE. Followup is necessary.

Date: 2/13/2014 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location at 11:38 2/13/14.

No visible sign of spill at the location described. Remediation determined to be complete.

No followup necessary.