

# Oil Field Environmental Incident Summary

**Incident:** 20140209231343      **Date/Time of Notice:** 02/09/2014 18:28

**Responsible Party:** Corcoran Oil field services

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** VACHAL 5-27H1

**Field Name:** ALKALI CREEK

**Well File #:** 26444

**Date Incident:** 2/8/2014      **Time Incident:** 12:10

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 154

**Rng:** 94

**Sec:** 22

**Qtr:** SW SE

**Location Description:** Road way coming out of location Vachal 5-27H-1

**Submitted By:** Brett Finnicum

**Received By:**

**Contact Person:** Mike Haunstien  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** No

**Reported to NRC:** Unknown

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	0	barrels	0	barrels		
<b>Brine</b>	3	barrels	3	barrels	3	barrels
<b>Other</b>	0	barrels	0	barrels		

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 10/14/2016      **Clean Up Concluded:** 2/10/2014

**Risk Evaluation:**

No immediate risks were present

**Areal Extent:**

the area contaminated was approx three and a half foot wide in spots to a trickle in others

**Potential Environmental Impacts:**

There was no impact to surface water and or ground water. The frozen road way was the main concern.

**Action Taken or Planned:**

Immediate response of Corcoran spill team was sent to location to assess and contain any hazards. After observation the plan was set to start by getting the proper equipment to handle the situation such as, payloader, roadgrader, 30 tons of class 5 rock and side dump to remove any and all contaminants off the road way. Added in our new daily driver pre trip inspection logs is going to stress valve wear inspection and cap inspection prior to leaving the yard for work.

**Wastes Disposal Location:** Oaks disposal

**Agencies Involved:**

**Updates**

---

**Date:** 2/10/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release from truck valve leak on lease road. Followup is necessary.

---

**Date:** 2/18/2014    **Status:** Inspection

**Author:** Miller, Adam

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

I inspected the location and there is an active frac job being done on the well. Because of the weather, there is serious road degradation and I am unable to find the exact spill location. I called Mike Haunstien of Continental Resources, and he stated that the spill has been cleaned up. No further followup is required.