

Oil Field Environmental Incident Summary

Incident: 20140220193639 **Date/Time of Notice:** 02/20/2014 19:28

Responsible Party: Hess Bakken Investments II, LLC

Well Operator: HESS BAKKEN INVESTMENTS II, LLC

Well Name: LK-ALWIN 147-97-1324H-3

Field Name: LITTLE KNIFE

Well File #: 22923

Date Incident: 2/20/2014 **Time Incident:** 0300

Facility ID Number:

County: DUNN

Twp: 147 **Rng:** 97 **Sec:** 13 **Qtr:**

Location Description:

Submitted By: Jason Dalen

Received By:

Contact Person: Brian Epperson
1501 MCKINNEY
HOUSTON, TX 77010

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Miles

Distance Nearest Water Well: 1 Miles

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	barrels	2	barrels	2	barrels
Brine	0	barrels	0	barrels		
Other	0	barrels	0	barrels		

Description of Other Released Contaminant:

Inspected:

Written Report Received: 4/21/2014

Clean Up Concluded: 3/6/2014

Risk Evaluation:

None

Areal Extent:

Oil spilled to the lease road just off location

Potential Environmental Impacts:

Temporary containment was set up around the spill until daylight, when clean-up commenced. Impact to soil.

Action Taken or Planned:

Temp containment around spill. Clean-up crew responded during daylight hours.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 2/21/2014 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

Date: 3/5/2014 **Status:** Inspection

Author: Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

3/5/2014 at 15:24, on location. East side of lease road has been scraped down to dirt; no visible staining within scraped area. No visible staining on vegetation or snow on either side of lease road outside of scraped areas or downhill from lease road.