

# Oil Field Environmental Incident Summary

**Incident:** 20140314110212      **Date/Time of Notice:** 03/14/2014 11:02

**Responsible Party:** TERVITA, LLC

**Well Operator:** TERVITA, LLC

**Well Name:** WASTE OIL TREATING PLANT

**Field Name:** N/A

**Well File #:**

**Date Incident:** 3/13/2014      **Time Incident:** 20:30

**Facility ID Number:** 550440-01

**County:** MOUNTRAIL

**Twp:** 156      **Rng:** 94      **Sec:** 7      **Qtr:**

**Location Description:**

**Submitted By:** Trevor Befus

**Received By:**

**Contact Person:** Trevor Befus  
500 - 140 10TH AVE SE  
CALGARY, AB T2G 0R1

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3	Barrels	3	Barrels		

**Brine**

**Other**

**Description of Other Released Contaminant:**

Crude Oil

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

Environmental release, low impact

**Areal Extent:**

**Potential Environmental Impacts:**

Low impact due to no nearby water sources / On-site release

**Action Taken or Planned:**

All impacted soils was removed from impacted area, resulting material was managed on-site at the facility - Final disposal will be landfill. A review of loading / unloading / transferring fluids was conducted with operations staff. Continuous monitoring of levels during the transfer / loading / unloading is required by operations.

**Wastes Disposal Location:** Initially on-site at the facility and will be disposed of at an approved landfill

**Agencies Involved:**

**Updates**

---

**Date:** 3/17/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

This site is not considered an E & P location. Followup is necessary.

---

**Date:** 4/3/2014    **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

4/3/2014 at 10:14, on location. Facility is actually located north of Alexander, ND. Discussed with report contact issues with online reporting database, resulting in location being mistakenly assigned to Mountrail County. Met with safety personnel and inspected site of incident. Release came out of central tank along south side of concrete containment. Impact to ground and bag containers; both have been disposed of. No stain currently visible on bags or facility ground. Concrete containment wall is stained, but no standing fluid is visible.