

# Oil Field Environmental Incident Summary

**Incident:** 20140315222845

**Date/Time of Notice:** 03/15/2014 22:28

**Responsible Party:** Eric

**Well Operator:**

**Well Name:**

**Field Name:** MCGREGOR

**Well File #:**

**Date Incident:** 3/15/2014

**Time Incident:** 11.00

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 130

**Rng:** 60

**Sec:** 1

**Qtr:**

**Location Description:** From 96th st to 93rd st west to

**Submitted By:** Brett Finnicum

**Received By:**

**Contact Person:** Brett Finnicum

Hagstrom

sidney

sidney, mt 59270

**General Land Use:** Other - Described Above

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** No

**Reported to NRC:** Unknown

**Spilled Units**

**Recovered Units**

**Followup Units**

**Oil**

**Brine** 5 Barrels

**Other**

**Description of Other Released Contaminant:**

Production water from down hole.

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

After driving the route of the spill there where no immediate risks of any kind.

**Areal Extent:**

There was approx. 5bbls of fluid leaked out of hose while driving down the gravel roads to disposal

**Potential Environmental Impacts:**

Very minimal environmental risk do to all fluid being on the road way in small amounts.

**Action Taken or Planned:**

Brought in company spill trailer in to clean up the bigger areas and took the right actions for proper disposal. Immediate termination of driver due to breaking company policies and safety regulations.

**Wastes Disposal Location:** There was minimum recover do to the fact that the road absorbed 90% of spill so you could not see where the spill occurred. Material that was recovered was taken to oaks disposal.

**Agencies Involved:** Local Law Enforcement

**Updates**

---

**Date:** 3/17/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of an E & P location. Followup is necessary.

---

**Date:** 3/18/2014    **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived at meeting location with Burke/Divide Deputy Sheriff at 13:00, 3/18/14. 30 degrees F, cloudy, NW wind 20-25 mph. Followed deputy sheriff to violation location, which was the ending location for the release. The location was on a gravel road (County Road 6). According to the deputy sheriff, the release started near a well pad, traveling north on 96th Avenue NW, turning west on 93rd Street NW, then north on 98th Avenue NW and ending turning west on County Road 6. The release extended approximately 6 miles. Two samples were collected from the surface of the gravel roads -- one from the deputy stop location and one from the surface of 96th Avenue NW, near the well pad. Follow up when lab results are received.

---

**Date:** 9/16/2015    **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived at furthest extent of release at 16:40. 63 degrees F, cloudy, SW wind 0-5 mph. Drove from furthest extent to release location, observing any impacts along roadway. No impacts were noted along the route. No further followup needed at this time.