

Oil Field Environmental Incident Summary

Incident: 20140423165732 **Date/Time of Notice:** 04/23/2014 16:57

Responsible Party: BOSQUE DISPOSAL SYSTEMS, LLC

Well Operator: BOSQUE DISPOSAL SYSTEMS, LLC

Well Name: JESSICA SWD 1

Field Name: BLUE BUTTES

Well File #: 90243

Date Incident: 11/22/2013 **Time Incident:** 04:02

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 95

Sec: 23

Qtr:

Location Description:

Submitted By: LoVonda Van Doren

Received By:

Contact Person: Mindi Wheeler
9025 ROARING CREEK RD
JOSHUA, TX 76058

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Pump Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	80	Barrels			80	barrels

Description of Other Released Contaminant:

Released Substance Oil / Saltwater

Inspected:

Written Report Received: 1/17/2017

Clean Up Concluded: 11/22/2013

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Cleaned up as much fluid as possible and then installed automation to prevent future spills.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 4/27/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

November, 2013 release remained on location, according to the report. NDIC retains oversight/response.