

Oil Field Environmental Incident Summary

Incident: 20140424152539 **Date/Time of Notice:** 04/24/2014 15:25

Responsible Party: Newfield Production Company

Well Operator: NEWFIELD PRODUCTION COMPANY

Well Name: LAWLAR 150-98-18-19-4H

Field Name: SIVERSTON

Well File #: 24997

Date Incident: 4/23/2014 **Time Incident:** 10:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 98

Sec: 7

Qtr: SE SW

Location Description:

Submitted By: Kumeko Doyle

Received By:

Contact Person: Kumeko Doyle
363 N. SAM HOUSTON, PKWY E
SUITE 100
HOUSTON, TX 77377

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	100	Barrels				
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

The water soaked into the gravel but there was a liner under the location and a liner under the tank battery and the pad is soil cement, so nothing actually penetrated the native soil.

Action Taken or Planned:

The small area of contaminated soil outside of the berm was shoveled up immediately. Currently the contaminated gravel inside the berm is being excavated and will be taken to Tervita Disposal.

Wastes Disposal Location: Tervita Disposal.

Agencies Involved:

Updates

Date: 4/27/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from an on-location valve/piping leak, remained on location, within the diking, according to the report. NDIC retains oversight.