

Oil Field Environmental Incident Summary

Incident: 20140428124215 **Date/Time of Notice:** 04/28/2014 12:42
Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Name: KIRKLAND 21-28TFH 3SH
Field Name: PERSHING **Well File #:** 22792
Date Incident: 4/24/2014 **Time Incident:** 16:00 **Facility ID Number:**
County: MCKENZIE **Twp:** 150 **Rng:** 96 **Sec:** 28 **Qtr:**
Location Description:

Submitted By: Gordon Marek **Received By:**
Contact Person: Rory Ketterling
PO BOX 51810
MIDLAND, TX 79710-1810

General Land Use: Well/Facility Site **Affected Medium:** Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site **Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	30	Gallons	1	Barrels		
Brine	5	Barrels	30	Gallons		

Other

Description of Other Released Contaminant:

Inspected: **Written Report Received:** **Clean Up Concluded:**

Risk Evaluation:

immediate risk to environment

Areal Extent:

Potential Environmental Impacts:

soil impact

Action Taken or Planned:

spill was sucked up of standing fluid. excavation of contaminated soil. replaced with clean material. well lines were pressure tested to ensure integrity. spill amount was calculated on Saturday (during clean up) With X Length XDepth and came with the 5 barrel amount.

Wastes Disposal Location: indian hills landfill

Agencies Involved: Conocophillips

Updates

Date: 4/28/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill remained on location. NDIC retains oversight.