

Oil Field Environmental Incident Summary

Incident: 20140429154612 **Date/Time of Notice:** 04/29/2014 15:46

Responsible Party: XTO ENERGY INC.

Well Operator: XTO ENERGY INC.

Well Name: THAXTON 24X-35F

Field Name: WEST CAPA

Well File #: 22515

Date Incident: 4/29/2014 **Time Incident:** 08:30

Facility ID Number:

County: WILLIAMS

Twp: 155 **Rng:** 97 **Sec:** 35 **Qtr:**

Location Description:

Submitted By: Kaylan Dirx

Received By:

Contact Person: Kaylan Dirx
P.O Box 1589
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels				

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None - spill was contained within the lined metal berm.

Areal Extent:

Potential Environmental Impacts:

None-spill was contained within the lined metal berm.

Action Taken or Planned:

Spill is contained within the lined metal berm. C-Company was contacted for cleanup.

Wastes Disposal Location: Indian Hills - Liquids

Agencies Involved:

Updates

Date: 4/30/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a tank overflow remained on location within the diking, according to the report. NDIC retains oversight.