

Oil Field Environmental Incident Summary

Incident: 20140507084123 **Date/Time of Notice:** 05/07/2014 08:41

Responsible Party: Zargon Oil (ND) INC.

Well Operator: ZARGON OIL (ND) INC.

Well Name: Macobee Coulee Madison Unit

Field Name: MACKOBEE COULEE

Well File #:

Date Incident: 5/6/2014 **Time Incident:** 09:50 **Facility ID Number:** 404406-01

County: RENVILLE **Twp:** 158 **Rng:** 85 **Sec:** 21 **Qtr:** SE NE

Location Description:

Submitted By: Josh Johnson

Received By:

Contact Person: Josh Johnson
700 333 5TH AVE SW
CALGARY, AB T2P 3B6

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	8	Barrels	8	Barrels	8	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 2/9/2017

Clean Up Concluded: 5/10/2014

Risk Evaluation:

No hazards. Water was sucked up immediately with water truck and gravel/soil was cleaned up and put in semi-sidedump.

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Spill was contained inside treater berm. All soil 1" thick was picked up and put in truck sidedump.

Wastes Disposal Location: Trevisa- Williston, ND

Agencies Involved:

Updates

Date: 5/7/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release from a treater leak remained on location according to the report. NDIC retains oversight.