

Oil Field Environmental Incident Summary

Incident: 20140507094859 **Date/Time of Notice:** 05/07/2014 09:48

Responsible Party: UNKNOWN

Well Operator: EOG RESOURCES, INC.

Well Name: VANVILLE 6-25H

Field Name: THOMPSON LAKE

Well File #: 18862

Date Incident: 5/6/2014 **Time Incident:** 17:57

Facility ID Number:

County: BURKE

Twp: 159

Rng: 91

Sec: 25

Qtr:

Location Description: This spill was discovered on the roadway outside of Summit Midstream's - North Compressor Station. On the dirt access road near the junction with HWY 50.

Submitted By: Andrew Parisi

Received By:

Contact Person: UNKNOWN UNKNOWN
UNKNOWN
UNKNOWN, ND UNKNOWN

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Unknown

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	15	Gallons	15	Gallons		

Description of Other Released Contaminant:

The substance appears to be a thick black sludge. Possibly bottom solids from inside a tanker truck.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Due to rain in the forecast, there is a potential to enter water stream if not cleaned up quickly.

Areal Extent:

There are spots sludge on the roadway, one of which is along the ditch on the side of the road.

Potential Environmental Impacts:

The soil on the roadway was impacted, and the dirt along the roadway ditch. The impacted area will be excavated tonight to avoid the material from washing down into the ditch, and into surface waters along the neighboring wheat field.

Action Taken or Planned:

Summit Midstream and EOG have a contractor on site at 19:00 PM to begin excavating the impacted soil. Summit Midstream is unsure who dumped this material on the road, but judging by the splash patterns, it appears that it may have splashed out of an open valve on the back of a tank truck. Both Summit Midstream and EOG did not have any trucks on site today that would have spilled this material. However, this spill was cleaned up immediately to avoid the sludge from entering the ditch once the rains start later this evening and continue into tomorrow.

Wastes Disposal Location: The impacted soil will be excavated and taken to the Prairie Disposal site for disposal. The Prairie Disposal location is located in the town of Tioga, ND.

Agencies Involved: Local Law Enforcement (Berk County Sheriff Dept.)

Updates

Date: 5/7/2014 **Status:** Reviewed - Follow-up Required **Author:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received incident call on emergency cell phone and on department phone. Summit Midstream has cleaned up the site, acting on a good neighbor policy. More followup is needed, however. Scott Stockdill to inspect during the week of 6/12/14.

Date: 6/25/2014 **Status:** Inspection **Author:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on scene 6/25/2014.

No sign of spill at the site. The site was cleaned up immediately by EOG and Summit Midstream staff.

No followup is necessary.