

Oil Field Environmental Incident Summary

Incident: 20140512100219 **Date/Time of Notice:** 05/12/2014 10:02

Responsible Party: ONEOK Rockies Midstream

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 5/8/2014 **Time Incident:** 11:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 95

Sec: 18

Qtr: SE

Location Description: Blue Buttes Compressor Station is located approximately 17 miles due east of Watford City, ND on Highway 73.

Submitted By: Mitch Anderson

Received By:

Contact Person: Mitch Anderson
2700 Lincoln Avenue SE
Sidney, MT 59270

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well: 1 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other 5 Gallons

Description of Other Released Contaminant:

Natural gas liquids

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

There were no immediate health hazards.

Areal Extent:

All of the condensate was captured inside the secondary containment structure.

Potential Environmental Impacts:

There were no adverse environmental impacts.

Action Taken or Planned:

The drain line was allowed to de-pressurize.

Wastes Disposal Location: Any and all recovered wastes will be transported to an licensed and approved landfill

Agencies Involved: McKenzie County LEPC Director

Updates

Date: 5/16/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release inside dike at a compressor station. Followup is necessary.

Date: 6/24/2014 **Status:** Inspection

Author: Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 9:25, off site 10:05. Cloudy, light rain, 56 degrees, light wind. No sign of any spill. Newly worked surfaces; clean clay and scoria gravel on all surfaces inside and outside of containment area and grounds. Surrounding grassed areas were green and healthy looking.