

Oil Field Environmental Incident Summary

Incident: 20140605070152 **Date/Time of Notice:** 06/05/2014 07:01

Responsible Party: EOG Resources, Inc.

Well Operator: EOG RESOURCES, INC.

Well Name: WAYZETTA 52-3334H

Field Name: PARSHALL

Well File #: 27776

Date Incident: 6/4/2014 **Time Incident:** 19:00

Facility ID Number:

County: MOUNTRAIL

Twp: 153

Rng: 90

Sec: 33

Qtr: NE NW

Location Description:

Submitted By: Luigi Heydt

Received By:

Contact Person: Luigi Heydt
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	40	Barrels	40	Barrels	40	barrels

Description of Other Released Contaminant:

Oil based mud

Inspected:

Written Report Received: 10/26/2015

Clean Up Concluded: 6/5/2014

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

All the mud was sucked up using a supersucker. The rig crew scraped the area using their loader, mixed the material with fly ash and placed it in their cuttings tank to be taken to disposal.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 6/5/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Drilling mud release remained on location according to report. NDIC retains oversight.