

# Oil Field Environmental Incident Summary

**Incident:** 20140625160039      **Date/Time of Notice:** 06/25/2014 16:00

**Responsible Party:** STATOIL OIL & GAS LP

**Well Operator:** STATOIL OIL & GAS LP

**Well Name:** JACK ERICKSON 6-31 1-H

**Field Name:** PAINTED WOODS

**Well File #:** 18439

**Date Incident:** 6/24/2014      **Time Incident:** 17:00

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 154

**Rng:** 102

**Sec:** 6

**Qtr:**

**Location Description:** an area approx 200' x 200' west of location (oil mist residue)

**Submitted By:** Mike McMillian

**Received By:**

**Contact Person:** Keith Bryan  
6300 BRIDGE POINT PKY, BLDG 2  
SUITE 500  
AUSTIN, TX 78730

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.3 Mile

**Distance Nearest Water Well:**

**Type of Incident:** Treater Leak

**Release Contained in Dike:** No

**Reported to NRC:** Unknown

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3.5	Barrels	3.5	Barrels	3.5	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 9/1/2016

**Clean Up Concluded:** 4/1/2015

**Risk Evaluation:**

none

**Areal Extent:**

an area that consist of approx 200' x 200' west of location (oil mist residue).

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

Action taken : Shut well in and contracted Phillips and Jordan (a professional environmental clean up company) to clean up spill. Future action : there will be a guard / shield installed over the top of the fire tube flange to prevent oil from spraying.

**Wastes Disposal Location:** PDI, Prairie Disposal Inc.

**Agencies Involved:**

**Updates**

---

**Date:** 6/25/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release sprayed off location. Followup is necessary.

---

**Date:** 7/1/2014    **Status:** Inspection

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

7/1/14 - 17:40 on location. Oil spray from treater went off the west side of the location into a tall grass area of the reported size. Company has scraped the perimeter berm where stained and has cut the impacted area vegetation. However, the cut vegetation has not been removed as of this date. Will contact the company to determine final cleanup.

---

**Date:** 4/1/2015    **Status:** Correspondence

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Email sent this date to incident contact requesting confirmation that impacted and cut vegetation had been removed and disposed.

---

**Date:** 11/5/2015    **Status:** Inspection

**Author:** Crowds, Kory

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On location 11/5/15, at 9:35 a.m. Walked area. No remaining impacts seen at this time. No impact or stress to vegetation noticed. No further followup required.