

# Oil Field Environmental Incident Summary

**Incident:** 20140810133141      **Date/Time of Notice:** 08/10/2014 13:31

**Responsible Party:** ONEOK Rockies Midstream

**Well Operator:**

**Well Name:**

**Field Name:**

**Well File #:**

**Date Incident:** 8/8/2014      **Time Incident:** 11:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 150      **Rng:** 95      **Sec:** 18      **Qtr:** SE

**Location Description:** Sandstone Compressor Station is located approximately 17 miles due east of Watford City, ND on Highway 23. It is adjacent to Blue Buttes Compressor Station on the north side of the highway.

**Submitted By:** Mitch Anderson

**Received By:**

**Contact Person:** Mitch Anderson  
2700 Lincoln Avenue SE  
Sidney, MT 59270

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	5	Barrels	5	Barrels		

**Description of Other Released Contaminant:**

Natural Gas Liquids

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

There were no immediate health hazards

**Areal Extent:**

The condensate was contained inside the secondary containment structure.

**Potential Environmental Impacts:**

There were no adverse environmental impacts.

**Action Taken or Planned:**

The liquids inside the secondary containment structure will be removed.

**Wastes Disposal Location:** The liquids will be transported off-site and transferred into an approved disposal well.

**Agencies Involved:** McKenzie County LEPC Director

**Updates**

---

**Date:** 8/11/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release of natural gas condensates from a pipeline leak. Followup is necessary.

---

**Date:** 8/21/2014    **Status:** Inspection

**Author:** Wax, Pete

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site 7:40, off site 8:45; heavy fog, calm, 62 degrees. Gate locked. Inspected north, west, and south sides of facility. Opening in fence 100 yards south of NW corner of facility where some new earth has been worked (both inside and outside) of facility grounds (took pictures). Entered through opening. No sign of oil on ground in this area (outside or inside) of fence. Area outside of fence reworked is approximately 40' by 100'. Recommend Oil and Gas lead.