

Oil Field Environmental Incident Summary

Incident: 20140813155628 **Date/Time of Notice:** 08/13/2014 15:56

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: BURKE 15-21H

Field Name: STANLEY

Well File #: 18073

Date Incident: 8/13/2014 **Time Incident:** 04:30

Facility ID Number:

County: MOUNTRAIL

Twp: 155

Rng: 90

Sec: 21

Qtr:

Location Description:

Submitted By: Matt Richards

Received By:

Contact Person: Matt Richards
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels	1	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/19/2015

Clean Up Concluded: 9/15/2014

Risk Evaluation:

None

Areal Extent:

100' x 30' area hit by spray off location

Potential Environmental Impacts:

None

Action Taken or Planned:

D & L was brought in to remove contaminated soil with bobcat and hauled off to clean harbors for disposal. Land owners were notified and decided to monitor the affected crop.

Wastes Disposal Location: Clean Harbors

Agencies Involved:

Updates

Date: 8/13/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Spray off location from an unspecified cause. Followup is necessary.

Date: 10/16/2014 **Status:** Inspection

Author: Wax, Pete

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On site 10:45; off site 11:10. Mostly cloudy, wind 15 mph from the NW, 40 degrees. Photographs collected. Nearest water is a permanent wetland that lies against the east and south edge of well pad. No storm water barrier to prevent runoff into wetland from facility, and southeast corner is open to drain into wetland. Walked entire perimeter of well pad. Only evidence of a release is immediately north of pumping unit. Evidence is minimal and includes: (1) a light coloring on a narrow strip (<1 x 4 paces) of standing canola missed during harvest or clipping (area runs the edge of well pad dike), and (2) a lack of vegetation in the borrow ditch along inside of well pad dike in same location. Walked north into harvested granola field and found no oil residue or staining on granola stubble or soil. Found no other evidence of any impacts off site. Suspected release not likely to impact surface or ground waters in the area.

Date: 4/18/2016 **Status:** Correspondence

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated April 18, 2016.