

# Oil Field Environmental Incident Summary

**Incident:** 20140818150620      **Date/Time of Notice:** 08/18/2014 15:06  
**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP  
**Well Name:** CCU BOXCAR CTB (CORRAL CREEK CTB)  
**Field Name:** CORRAL CREEK      **Well File #:**  
**Date Incident:** 8/17/2014      **Time Incident:** 16:15      **Facility ID Number:** 416647-06  
**County:** DUNN      **Twp:** 147      **Rng:** 95      **Sec:** 22      **Qtr:** SW SW  
**Location Description:** adjacent to the east side of the Central Tank Battery pad.

**Submitted By:** Lewis Schoenberger      **Received By:**  
**Contact Person:** Lewis Schoenberger  
PO BOX 51810  
MIDLAND, TX 79710-1810

**General Land Use:** Well/Facility Site      **Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 0.5 Mile  
**Distance Nearest Water Well:** 0.5 Mile

**Type of Incident:** Other

**Release Contained in Dike:** No      **Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2	Barrels				
<b>Brine</b>						
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 8/3/2016      **Clean Up Concluded:** 8/19/2014

**Risk Evaluation:**  
None

**Areal Extent:**  
approximately 15 feet by 55 feet was covered with an oily mist.

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Oil impacted vegetation will be collected for appropriate disposal.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 8/19/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted areas off of location. Followup is necessary.

---

**Date:** 8/22/2014    **Status:** Inspection

**Author:** Wax, Pete

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

On site 09:50; off site 10:30; wind north at 5 mph, overcast, precipitating, and dense fog. Site manager on site. Area that received spray was on east edge of well pad. Spray traveled over the top of the dike and down the outside slope, but there is no evidence it reached beyond the fence of the well site. Affected area was covered until cleanup was started. Cleanup included removing the surface-impacted soil, and clipping, bagging and disposing of sprayed vegetation. Earth has been reshaped nicely. Grass looks clean.