

Oil Field Environmental Incident Summary

Incident: 20140911075015 **Date/Time of Notice:** 09/11/2014 07:50

Responsible Party: Key Energy Services

Well Operator: KEY ENERGY SERVICES, LLC

Well Name: George Tank SWD #1

Field Name: KEENE

Well File #: 3680

Date Incident: 8/18/2014 **Time Incident:** 07:45

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 96

Sec: 27

Qtr: NE SE

Location Description: From McKinzie County Road 12 and Hwy 23 south 1.2 miles and west 600 feet to facility

Submitted By: Jerry Sparling

Received By:

Contact Person: Jerry Sparling

6389 104th ave. NW

1301 McKinney suite 1800 Houston Tx. 77010

Tioga, ND 58852

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 500 Feet

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels	3	Barrels	3	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 12/9/2015

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

The valve has been changed and tested. The electrical and warning systems have been inspected and tested. The customer has been reoriented on the facility and regular check of the system are completed

Wastes Disposal Location: Indian Hills Land Recovery Facility

Agencies Involved:

Updates

Date: 9/11/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.