

# Oil Field Environmental Incident Summary

**Incident:** 20140911174131      **Date/Time of Notice:** 09/11/2014 17:41

**Responsible Party:** HESS BAKKEN INVESTMENTS II, LLC

**Well Operator:** HESS BAKKEN INVESTMENTS II, LLC

**Well Name:** EN-STATE C/RIERSGARD-156-93 TEST FACILITY

**Field Name:** ALGER

**Well File #:**

**Date Incident:** 9/10/2014      **Time Incident:** 15:45      **Facility ID Number:** 216928-08

**County:** MOUNTRAIL      **Twp:** 156      **Rng:** 93      **Sec:** 16      **Qtr:** NW SW

**Location Description:**

**Submitted By:** Jason Henry

**Received By:**

**Contact Person:** Jason Henry  
1501 MCKINNEY  
HOUSTON, TX 77010

**General Land Use:** Well/Facility Site

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.4 Mile

**Distance Nearest Water Well:** 0.4 Mile

**Type of Incident:** Fire

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1	Barrels			1	barrels

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**      **Written Report Received:** 5/16/2016      **Clean Up Concluded:** 9/19/2014

**Risk Evaluation:**

The crude oil which was discharged through the flare stack and caught fire was extinguished immediately after the incident occurred.

**Areal Extent:**

Approximately 40 feet by 40 feet to the west of the location in the form of an aerial mist.

**Potential Environmental Impacts:**

There was no surface water observed in the immediate vicinity of the release location. The impacted soil will be excavated and disposed of at a properly permitted disposal facility.

**Action Taken or Planned:**

The impacted soil will be excavated and disposed of at a properly permitted disposal facility.

**Wastes Disposal Location:** At a properly permitted disposal facility.

**Agencies Involved:**

**Updates**

---

**Date:** 9/12/2014    **Status:** Reviewed - Follow-up Required

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill impacted the surrounding area. Followup is necessary.

---

**Date:** 10/1/2014    **Status:** Inspection

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location at 15:00 CT. Observed site and took photos. Could not determine the 40-foot by 40-foot area impacted west of the flares. However, a very small amount of the release was noted on a couple of the steel fence posts west of the flares. Released materials should naturally attenuate, due to unobservable amounts on the wheat straw west of the fence. Left message with company contact to determine whether wheat was harvested before or after the incident. On-site followup not required.