

# Oil Field Environmental Incident Summary

**Incident:** 20140912084217      **Date/Time of Notice:** 09/12/2014 08:42

**Responsible Party:** Rockwater Energy Services

**Well Operator:** OXY USA INC.

**Well Name:** WILLIAM SADOWSKY 2-9-4H-142-96

**Field Name:** MANNING

**Well File #:** 27957

**Date Incident:** 9/11/2014      **Time Incident:** 18:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 142

**Rng:** 96

**Sec:** 9

**Qtr:**

**Location Description:**

**Submitted By:** Dustin Tescher

**Received By:**

**Contact Person:** Dustin Tescher  
2592 4th street east  
Dickinson, ND 58601

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	2	Barrels	1	Barrels		
<b>Other</b>						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

NA

**Areal Extent:**

**Potential Environmental Impacts:**

NA

**Action Taken or Planned:**

The tank hatch was secured to prevent any further releases.

**Wastes Disposal Location:**

**Agencies Involved:**

**Updates**

---

**Date:** 9/12/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.