

# Oil Field Environmental Incident Summary

**Incident:** 20140921181155      **Date/Time of Notice:** 09/21/2014 18:11

**Responsible Party:** SAMSON RESOURCES COMPANY

**Well Operator:** SAMSON RESOURCES COMPANY

**Well Name:** BONNEVILLE Central Tank Battery

**Field Name:** WEST AMBROSE

**Well File #:**

**Date Incident:** 9/19/2014      **Time Incident:** 11:00      **Facility ID Number:** 219965-01

**County:** DIVIDE      **Twp:** 163      **Rng:** 100      **Sec:** 36      **Qtr:** SE SW

**Location Description:** Central Tank Battery

**Submitted By:** Brad Rogers

**Received By:**

**Contact Person:** Kerry Bjorgen  
2 W 2ND ST SAMSON PLAZA  
TULSA, OK 74103-3101

**General Land Use:** Pasture

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

|            | <b>Spilled</b> | <b>Units</b> | <b>Recovered</b> | <b>Units</b> | <b>Followup</b> | <b>Units</b> |
|------------|----------------|--------------|------------------|--------------|-----------------|--------------|
| <b>Oil</b> | 5              | Barrels      | 4                | Barrels      | 30              | gallons      |

**Brine**

**Other**

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:** 9/7/2016

**Clean Up Concluded:** 9/20/2014

**Risk Evaluation:**

No immediate risks

**Areal Extent:**

200' x 50'

**Potential Environmental Impacts:**

Impact to grass and soil off location of CTB.

**Action Taken or Planned:**

Well shut in to fix meter. Grass with oil mist will be mowed and bagged. Any impacted soils will be removed and disposed of at approved disposal facility. Booms will be placed on outer edge of spill to prevent any oil runoff in case of rain.

**Wastes Disposal Location:** At approved disposal facility. 13-Mile Landfill north of Williston.

**Agencies Involved:**

**Updates**

---

**Date:** 9/23/2014    **Status:** Reviewed - Follow-up Required

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Oil spray off location. Followup is necessary.

---

**Date:** 9/25/2014    **Status:** Inspection

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

9/25/14 - 14:00 on location. Spray from the flare system to the E-NE, as described. Impacted vegetation removed and absorbent booms deployed to ensure containment. No impacts beyond mowed area. No further inspections necessary.