

Oil Field Environmental Incident Summary

Incident: 20141016164753 **Date/Time of Notice:** 10/16/2014 16:47

Responsible Party: Targa Resources

Well Operator:

Well Name:

Field Name:

Well File #:

Date Incident: 10/14/2014 **Time Incident:** 10:43

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 96

Sec: 24

Qtr: NW NW

Location Description: Targa Resource Johnsons Corner Crude Oil Terminal, one mile east of highway 73 and McKenzie county road 53 junction

Submitted By: Mark Glaser

Received By:

Contact Person: Mark Glaser
1939 125th Ave. W.
Watford City, ND 58854

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1750 Feet

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	25	Gallons	25	Gallons		

Brine

Other

Description of Other Released Contaminant:

N/A

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

N/A

Potential Environmental Impacts:

Oil was contained within driving lane of the truck loading rack. Compacted gravel.

Action Taken or Planned:

Volume of crude oil spilled was small enough that it didnt leave the driving lane of the truck loading rack. Contaminated dirt was excavated, stockpiled, and contained within the working area of the terminal. Once analytical profiles are complete, waste will be hauled to an approved disposal facility.

Wastes Disposal Location: Wastes will be hauled to a NDDH approved waste disposal i.e. Prairie Disposal, Sawyer Disposal, or Indian Hills.

Agencies Involved: ND Department of Health

Updates

Date: 10/18/2014 **Status:** Reviewed - Follow-up Required

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, remained on location within the diking according to the report. This is at a crude oil terminal and not within jurisdiction of the NDIC. Followup is necessary.

Date: 10/21/2014 **Status:** Awaiting Documentation

Author: Cooper, Mike

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on site at 3:45 CT. Temp 72 degrees, wind 5-10 mph. Inspected area and took pictures. Spill has been excavated, and the contaminated material/boom (2-3 yds) is stockpiled on site in a 25-yd rolloff bin. Material is waiting to be taken to PDI. No visible evidence of a spill is present. Awaiting documentation from Targa Resources (disposal facility).