

# Oil Field Environmental Incident Summary

**Incident:** 20141020132355      **Date/Time of Notice:** 10/20/2014 13:23

**Responsible Party:** PETRO-HUNT, L.L.C.

**Well Operator:** PETRO-HUNT, L.L.C.

**Well Name:** USA 5D-4-4HR

**Field Name:** CHARLSON

**Well File #:** 11983

**Date Incident:** 10/18/2014      **Time Incident:** 20:00

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 153

**Rng:** 95

**Sec:** 5

**Qtr:**

**Location Description:** No Spill, This was a fire which consumed the treater house.

**Submitted By:** Doug Hanson

**Received By:**

**Contact Person:** Doug Hanson

PO BOX 935

BISMARCK, ND 58502

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 2 Mile

**Distance Nearest Water Well:** 2 Mile

**Type of Incident:** Fire

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

Spilled	Units	Recovered	Units
---------	-------	-----------	-------

Followup	Units
----------	-------

Oil

Brine

Other

**Description of Other Released Contaminant:**

No released substance, this was a fire.

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

NA

**Areal Extent:**

NA

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

The treater will be replaced.

**Wastes Disposal Location:** There will not be any wastes. However there might be some burned soil and scoria. It has not been contaminated

**Agencies Involved:** Local Fire Department

**Updates**

---

**Date:** 10/27/2014 **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Fire on location but no fluid release according to the report. NDIC retains oversight.