

Oil Field Environmental Incident Summary

Incident: 20141031171123 **Date/Time of Notice:** 10/31/2014 17:11

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: PARSHALL 23-3029H

Field Name: PARSHALL

Well File #: 29263

Date Incident: 10/30/2014 **Time Incident:** 19:45

Facility ID Number:

County: MOUNTRAIL

Twp: 152

Rng: 90

Sec: 30

Qtr: NW NE

Location Description:

Submitted By: Keith Kallberg

Received By:

Contact Person: Keith Kallberg
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	175	Barrels	155	Barrels	175	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 10/26/2015

Clean Up Concluded: 11/24/2015

Risk Evaluation:

Low

Areal Extent:

Potential Environmental Impacts:

Low

Action Taken or Planned:

When he came back he realized what he did and shut down the mix pump. Free fluids were sucked up and put back into the system and the affected area was scraped and put into the cuttings bin.

Wastes Disposal Location: Free fluids were put back into the system and solids to Tervita Disposal

Agencies Involved: TAT and MHA

Updates

Date: 10/31/2014 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to unspecified cause, remained on location according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.