

# Oil Field Environmental Incident Summary

**Incident:** 20141102142927      **Date/Time of Notice:** 11/02/2014 14:29

**Responsible Party:** CONTINENTAL RESOURCES, INC.

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** HOLTE 4-32H

**Field Name:** STONEVIEW

**Well File #:** 28086

**Date Incident:** 11/2/2014      **Time Incident:** 04:45

**Facility ID Number:**

**County:** DIVIDE

**Twp:** 160

**Rng:** 95

**Sec:** 32

**Qtr:**

**Location Description:**

**Submitted By:** Shane Knuchel

**Received By:**

**Contact Person:** Shane Knuchel  
PO BOX 268870  
OKLAHOMA CITY, OK 73126

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Tank Overflow

**Release Contained in Dike:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	3	Barrels	3	Barrels		

**Description of Other Released Contaminant:**

Slickwater used in completions activities containing FR and biocide.

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Environmental Impacts:**

Well site soil.

**Action Taken or Planned:**

Fluid was recovered using vac skid. Pumper notified to be more careful.

**Wastes Disposal Location:** All wastes were recovered.

**Agencies Involved:** Notified Richard Dunn by phone NDIC 11/2/2014 at 9:00 AM

**Updates**

---

**Date:** 11/3/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to a tank overflow apparently during fracking activities, remained on location according to the report. NDIC retains oversight.