

# Oil Field Environmental Incident Summary

**Incident:** 20141103153044      **Date/Time of Notice:** 11/03/2014 15:30

**Responsible Party:** DENBURY ONSHORE, LLC

**Well Operator:** DENBURY ONSHORE, LLC

**Well Name:** CHSU 21-1NH 16

**Field Name:** CEDAR HILLS

**Well File #:** 15241

**Date Incident:** 11/2/2014      **Time Incident:** 14:58

**Facility ID Number:**

**County:** BOWMAN

**Twp:** 131

**Rng:** 106

**Sec:** 1

**Qtr:**

**Location Description:** On location

**Submitted By:** Josh Cuppy

**Received By:**

**Contact Person:** Josh Cuppy  
5320 LEGACY DR  
PLANO, TX 75024-3127

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>					100	barrels
<b>Other</b>	100	Barrels				

**Description of Other Released Contaminant:**

Harr Source water

**Inspected:**

**Written Report Received:** 2/17/2016

**Clean Up Concluded:** 11/20/2014

**Risk Evaluation:**

None

**Areal Extent:**

On location

**Potential Environmental Impacts:**

None

**Action Taken or Planned:**

Shut in injection line. All fluid soaked into location.

**Wastes Disposal Location:**

**Agencies Involved:** BLM

**Updates**

---

**Date:** 11/4/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.