

# Oil Field Environmental Incident Summary

**Incident:** 20141130100108      **Date/Time of Notice:** 11/30/2014 10:01

**Responsible Party:** HRC Operating, LLC

**Well Operator:** HRC OPERATING, LLC

**Well Name:** CARLSON 1-11H

**Field Name:** STRANDAHL

**Well File #:** 19169

**Date Incident:** 11/29/2014      **Time Incident:** 13:15

**Facility ID Number:**

**County:** WILLIAMS

**Twp:** 157

**Rng:** 103

**Sec:** 11

**Qtr:** NW NW

**Location Description:** Small area SE of flare adjacent to well pad. Constructed well pad

**Submitted By:** Kelly Grimm

**Received By:**

**Contact Person:** Chris Marinez  
1801 California St  
Suite 3500  
Denver, CO 80202

**General Land Use:** Cultivated

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 0.7 Mile

**Distance Nearest Water Well:** 0.7 Mile

**Type of Incident:** Other

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	15	Gallons	15	Gallons	15	gallons

**Brine**

**Other**

**Description of Other Released Contaminant:**

Impacted snow cover will also removed.

**Inspected:**

**Written Report Received:** 11/27/2015

**Clean Up Concluded:** 11/30/2014

**Risk Evaluation:**

No immediate health risks

**Areal Extent:**

30'x75' area SE of constructed well pad

**Potential Environmental Impacts:**

No ground/surface water impacts

**Action Taken or Planned:**

Close line to flare when testing treater

**Wastes Disposal Location:** E&P Approved disposal

**Agencies Involved:** NDDoH

**Updates**

---

**Date:** 12/1/2014    **Status:** Reviewed - Assigned to Other Agency

**Author:** Roberts, Kris

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release sprayed off location to the SE of the well pad. Followup is necessary.