

Oil Field Environmental Incident Summary

Incident: 20141130142758 **Date/Time of Notice:** 11/30/2014 14:27

Responsible Party: TERVITA, LLC

Well Operator: TERVITA, LLC

Well Name: CCS Midstream Treatment Plant #1

Field Name: BLUE BUTTES

Well File #:

Date Incident: 11/28/2014 **Time Incident:** 17:20

Facility ID Number: 700079-01

County: MCKENZIE

Twp: 150

Rng: 96

Sec: 1

Qtr: S2 NE

Location Description: Spill occurred on 108th Ave, which is the street directly east of the Facility (Tervita Blue Buttes Landfill). NOTE: this spill did not actually occur on the Facility footprint, it occurred on the road by a truck (contracted by Tervita) that was filled with oilfield waste and headed towards the Landfill Facility for disposal.

Submitted By: Caitlin Hevey

Received By:

Contact Person: Jordan Becker

500 - 140 10TH AVE SE

CALGARY, AB T2G 0R1

General Land Use: Well/Facility Site

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Truck Overflow

Release Contained in Dike: Unknown

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	1	Barrels	1	Barrels		

Description of Other Released Contaminant:

Truck was transporting oilfield waste to landfill for disposal. Truck downshifted on a hill causing settled fluid to spill over onto the road.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None. All waste was contained on frozen road surface, and all waste and impacted material was cleaned up and disposed of properly.

Areal Extent:

Spill did not occur within engineered containment, however all impacted road surface was cleaned.

Potential Environmental Impacts:

None. All waste was contained on frozen road surface, and all waste and impacted material was cleaned up and disposed of properly.

Action Taken or Planned:

All waste material and impacted road surface was cleaned up immediately after the incident was reported. All waste material was disposed of properly at the landfill.

Wastes Disposal Location: Waste was disposed at the Tervita Blue Buttes Landfill facility, which is where the truck was heading with the load of waste that caused the incident.

Agencies Involved:

Updates

Date: 12/1/2014 **Status:** Reviewed - Assigned to NDDoH Division **Author:** Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release of a waste product in transport to a road surface. Report indicates immediate cleanup. Followup is referred to the NDDoH, Division of Waste Management.

Date: 1/12/2015 **Status:** Correspondence **Author:** Martin, Russell

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Followup email from responsible party. Incident location should be T151N R96W Sec. 25. Original location in report is Blue Buttes landfill; however, incident occurred north of the landfill.